



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southeast  
County: Ozaukee  
Site ID: 2-45-203-6  
Facility Type: Hi-Arch  
Site Address: W4074 County Rd. Z, Fredonia  
Date: March 9, 2016  
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	Multiple large cracks and potholes.					X
Ceiling and Roof	None		X			
Walls	None		X			
Doors	None		X			



Apron and Pad



Apron and Pad



Apron and Pad



Apron and Pad