

Wisconsin Department of Transportation Salt Shed Facilities Asset Management Condition Inspection Report



Region: County: Site ID: Facility Type: Site Address: Date: Inspector: <u>Northwest</u> <u>Pierce</u> <u>6-47-36-1</u> <u>Shed</u> <u>N1857 830<sup>th</sup> St., Hager City</u> <u>February 25, 2016</u> <u>Marcus Hopkins</u>

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	Moderate cracking on apron.				Х	
Ceiling and Roof	None		Х			
Walls	None		Х			
Doors	None		Х			

