



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest  
County: Polk  
Site ID: 8-48-41-1  
Facility Type: Shed  
Site Address: 518 Main Street, Balsam Lake  
Date: March 24, 2016  
Inspector: Todd Laska


Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	None		X			
Ceiling and Roof	Weathered shingles.				X	
Walls	Back wall bowed out.				X	
Doors	None		X			



Ceiling and Roof



Ceiling and Roof



Walls



Walls