



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central
County: Price
Site ID: 7-50-17-1
Facility Type: Shed
Site Address: 704 N. Lake Ave., Phillips
Date: March 10, 2016
Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	Large area of weathered shingles.				X	
Walls	None		X			
Doors	None		X			



Roof and Ceiling



Roof and Ceiling