



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southeast
County: Racine
Site ID: 2-51-1-1
Facility Type: Shed
Site Address: 31929 Academy Rd., Rochester
Date: February 11, 2016
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	None	X				
Walls	None		X			
Doors	None		X			