



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southeast
County: Racine
Site ID: 2-51-2-6
Facility Type: Shed
Site Address: 14200 Washington Ave., Sturtevant
Date: February 9, 2016
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	Large cracks over approximately 50% of apron.				X	
Ceiling and Roof	Weathered shingles			X		
Walls	None		X			
Doors	None		X			



Apron and Pad



Apron and Pad



Apron and Pad



Ceiling and Roof