



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest
County: Richland
Site ID: 5-52-766-2
Facility Type: Shed
Site Address: 29744 USH 14, Lone Rock
Date: March 9, 2016
Inspector: Eric Schmidt

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	Some cracks; portion of pavement recently repaired.			X		
Ceiling and Roof	None		X			
Walls	Slightly bowed.			X		
Doors	None		X			



Apron and Pad



Walls