



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest
County: Richland
Site ID: 5-52-767-1
Facility Type: Shed
Site Address: 13425 STH 58, Cazenovia
Date: March 8, 2016
Inspector: Eric Schmidt

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	Apron starting to crack.			X		
Ceiling and Roof	Shingles missing.				X	
Walls	None		X			
Doors	None		X			



Apron and Pad



Ceiling and Roof