



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest
County: Richland
Site ID: 5-52-768-1
Facility Type: Hi-Arch
Site Address: 120 Bowen Circle Drive, Richland Center
Date: March 9, 2016
Inspector: Eric Schmidt

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	Multiple cracks; some small potholes.				X	
Ceiling and Roof	None		X			
Walls	None		X			
Doors	No door.					X



Apron and Pad



Doors