



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest
County: Rock
Site ID: 1-53-481-1
Facility Type: Shed
Site Address: 1903 S. Read Rd., Janesville
Date: February 16, 2016
Inspector: Phil Eagan

| Asset | Comments | 1 – Excellent | 2 - Good | 3 – Okay | 4 – Poor | 5 – Bad |
|------------------|--------------------------------------|---------------|----------|----------|----------|---------|
| Apron and Pad | None | | X | | | |
| Ceiling and Roof | None | | X | | | |
| Walls | See photo, small hole in south wall. | | | X | | |
| Doors | None | | X | | | |



Walls