



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest  
County: St. Croix  
Site ID: 6-55-21-1  
Facility Type: Shed  
Site Address: 581 State Rd. 128, Wilson  
Date: February 10, 2016  
Inspector: Marcus Hopkins

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	None	X				
Ceiling and Roof	None	X				
Walls	None	X				
Doors	None		X			