



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest
County: St. Croix
Site ID: 6-55-5-1
Facility Type: Shed
Site Address: 666 USH 12E, Hudson
Date: February 11, 2016
Inspector: Marcus Hopkins

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	None		X			
Ceiling and Roof	None	X				
Walls	None	X				
Doors	None	X				