



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest  
County: Sauk  
Site ID: 1-56-120-3  
Facility Type: Shed  
Site Address: 620 State Rd. 136, Baraboo  
Date: March 29, 2016  
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	Curling shingles on west side of roof.				X	
Walls	None		X			
Doors	None		X			



Ceiling and Roof