



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest  
County: Sauk  
Site ID: 1-56-292-1  
Facility Type: Shed  
Site Address: S1616 State Rd. 23, Lake Delton  
Date: March 28, 2016  
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
<b>Apron and Pad</b>	Large cracks over approximately 50% of apron.				X	
<b>Ceiling and Roof</b>	None		X			
<b>Walls</b>	None		X			
<b>Doors</b>	None		X			



Apron and Pad



Apron and Pad