



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest  
County: Sauk  
Site ID: 1-56-292-3  
Facility Type: Dome  
Site Address: S1616 State Rd. 23, Lake Delton  
Date: March 28, 2016  
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	None		X			
Walls	None	X				
Doors	None		X			