



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central  
County: Shawano  
Site ID: 3-58-97-2  
Facility Type: Shed  
Site Address: N2388 Tile Dr., Angelica  
Date: February 18, 2016  
Inspector: Eric Schmidt

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	Cracking in asphalt >25' in front of shed.			X		
Ceiling and Roof	None		X			
Walls	None		X			
Doors	None		X			



Apron and Pad