



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northeast  
County: Sheboygan  
Site ID: 3-59-315-1  
Facility Type: Shed  
Site Address: N7563 State Road 42, Sheboygan  
Date: March 22, 2016  
Inspector: Marcus Hopkins

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	Pad beginning to crack in multiple locations.			X		
Ceiling and Roof	None		X			
Walls	None		X			
Doors	None		X			



Apron and Pad