



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report




Region: Northeast
County: Sheboygan
Site ID: 3-59-315-4
Facility Type: Shed
Site Address: N7563 State Road 42, Sheboygan
Date: March 22, 2016
Inspector: Marcus Hopkins

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	Some cracks in apron.		X			
Ceiling and Roof	None		X			
Walls	None		X			
Doors	Wood is chipping and peeling apart.			X		



Apron and Pad



Doors