



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northeast  
County: Sheboygan  
Site ID: 3-59-59-1  
Facility Type: Shed  
Site Address: 7614 Frontage Road, Sheboygan  
Date: March 22, 2016  
Inspector: Marcus Hopkins

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	None		X			
Walls	None		X			
Doors	None		X			