



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest  
County: Taylor  
Site ID: 6-60-1-7  
Facility Type: Hi-Arch  
Site Address: 209 N. 8<sup>th</sup> St., Medford  
Date: March 7, 2016  
Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	None		X			
Walls	None		X			
Doors	None		X			