



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest
County: Taylor
Site ID: 6-60-2-1
Facility Type: Shed
Site Address: 811 Kennedy, Rib Lake
Date: March 7, 2016
Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	None		X			
Walls	None		X			
Doors	Holes/cracks in door; one side temporarily patched with sheet of plywood.				X	



Doors