



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest
County: Trempealeau
Site ID: 5-61-803-1
Facility Type: Shed
Site Address: 50524 Honey Lane, Osseo
Date: March 21, 2016
Inspector: Phil Eagan

| Asset | Comments | 1 – Excellent | 2 - Good | 3 – Okay | 4 – Poor | 5 – Bad |
|------------------|---|---------------|----------|----------|----------|---------|
| Apron and Pad | Large cracks over approximately 75% of apron. | | | | | X |
| Ceiling and Roof | None | | X | | | |
| Walls | None | | X | | | |
| Doors | None | | X | | | |



Apron and Pad



Apron and Pad