



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest
County: Trempealeau
Site ID: 5-61-807-1
Facility Type: Shed
Site Address: 306 West Birch Street, Strum
Date: March 21, 2016
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	Cracks over approximately 50% of apron.				X	
Ceiling and Roof	None	X				
Walls	None		X			
Doors	None		X			



Apron and Pad