

Wisconsin Department of Transportation Salt Shed Facilities Asset Management Condition Inspection Report



Region: County: Site ID: Facility Type: Site Address: Date: Inspector:

Southwest Vernon 5-62-889-3 Hi-Arch S4393 Railroad Avenue, Viroqua March 08, 2016 Eric Schmidt

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		Х			
Ceiling and Roof	None		Х			
Walls	None		Х			
Doors	None		Х			