



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central  
County: Vilas  
Site ID: 7-63-20-1  
Facility Type: Shed  
Site Address: 1871 USH 45 N, Eagle River  
Date: March 8, 2016  
Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	None		X			
Walls	Bracing on west wall.			X		
Doors	No door.					X



Walls



Doors