



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central
County: Vilas
Site ID: 7-63-20-2
Facility Type: Shed
Site Address: 1871 USH 45 N, Eagle River
Date: March 8, 2016
Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	Some larger cracks beginning to develop; older cracks have been sealed.			X		
Ceiling and Roof	None		X			
Walls	None		X			
Doors	No door.					X



Apron and Pad



Apron and Pad



Apron and Pad



Doors