



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southeast
County: Walworth
Site ID: 2-64-109-1
Facility Type: Dome
Site Address: W1490 CTH L, East Troy
Date: February 17, 2016
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	Large cracks and some potholes over approximately 80% of apron.					X
Ceiling and Roof	None		X			
Walls	None	X				
Doors	None		X			



Apron and Pad



Apron and Pad