



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southeast  
County: Walworth  
Site ID: 2-64-203-11  
Facility Type: Dome  
Site Address: W4097 CTH NN, Elkhorn  
Date: February 17, 2016  
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	Large cracks and a few potholes over approximately 40% of apron.				X	
Ceiling and Roof	See photo.	X				
Walls	None	X				
Doors	None	X				



Apron and Pad