



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southeast
County: Walworth
Site ID: 2-64-203-3
Facility Type: Dome
Site Address: W4097 CTH NN, Elkhorn
Date: February 17, 2016
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	None		X			
Ceiling and Roof	None	X				
Walls	None		X			
Doors	None		X			