



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest  
County: Washburn  
Site ID: 8-65-98-1  
Facility Type: Hi-Arch  
Site Address: 1600 County Rd. H, Spooner  
Date: March 21, 2016  
Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
<b>Apron and Pad</b>	None		X			
<b>Ceiling and Roof</b>	None		X			
<b>Walls</b>	None		X			
<b>Doors</b>	None		X			