



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southeast
County: Washington
Site ID: 2-66-102-3
Facility Type: Dome
Site Address: 314 West Washington Street, Slinger
Date: March 7, 2016
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	None	X				
Ceiling and Roof	None	X				
Walls	None	X				
Doors	None	X				