



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southeast
County: Waukesha
Site ID: 2-67-2-2
Facility Type: Dome
Site Address: N51 W23093 Lisbon Rd., Sussex
Date: February 24, 2016
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	None	X				
Ceiling and Roof	None		X			
Walls	None		X			
Doors	No door					X



Doors