



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southeast  
County: Waukesha  
Site ID: 2-67-205-1  
Facility Type: Dome  
Site Address: N46 W33480 East Wisconsin Ave., Nashotah  
Date: February 22, 2016  
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	None		X			
Ceiling and Roof	A few missing shingles			X		
Walls	None		X			
Doors	No door.					X



Ceiling and Roof



Doors