

Wisconsin Department of Transportation Salt Shed Facilities Asset Management Condition Inspection Report



Region:SoutheastCounty:WaukeshaSite ID:2-67-4-1Facility Type:ShedSite Address:126 North Oakridge Drive, North PrairieDate:February 22, 2016Inspector:Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	None		Х			
<b>Ceiling and Roof</b>	None		Х			
Walls	None		Х			
Doors	No door.					Х

