



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central  
County: Waupaca  
Site ID: 4-68-17-2  
Facility Type: Shed  
Site Address: 600 East Fulton Street, Waupaca  
Date: March 16, 2016  
Inspector: Marcus Hopkins

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	None		X			
Ceiling and Roof	Trusses were damaged, but have been repaired.			X		
Walls	None		X			
Doors	None		X			



Ceiling and Roof