



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central
County: Waupaca
Site ID: 4-68-20-3
Facility Type: Shed
Site Address: 1006 West Wolf River Avenue, New London
Date: March 16, 2016
Inspector: Marcus Hopkins

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	None		X			
Ceiling and Roof	None		X			
Walls	None		X			
Doors	None		X			