



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central
County: Waushara
Site ID: 4-69-56-5
Facility Type: Shed
Site Address: N4101 State Rd. 49 South, Poy Sippi
Date: March 17, 2016
Inspector: Marcus Hopkins

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	Apron is moderately to severely cracked.				X	
Ceiling and Roof	None		X			
Walls	None		X			
Doors	None		X			



Apron and Pad