



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central  
County: Waushara  
Site ID: 4-69-59-2  
Facility Type: Shed  
Site Address: 227 W North Lake Rd. (County Rd. V), Hancock  
Date: March 17, 2016  
Inspector: Marcus Hopkins

| Asset            | Comments                     | 1 – Excellent | 2 - Good | 3 – Okay | 4 – Poor | 5 – Bad |
|------------------|------------------------------|---------------|----------|----------|----------|---------|
| Apron and Pad    | Apron is moderately cracked. |               |          | X        |          |         |
| Ceiling and Roof | None                         |               | X        |          |          |         |
| Walls            | None                         |               | X        |          |          |         |
| Doors            | None                         |               | X        |          |          |         |



Apron and Pad