



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northeast  
County: Winnebago  
Site ID: 3-70-393-1  
Facility Type: Hi-Arch  
Site Address: 1409 STH 26, Oshkosh  
Date: March 14, 2016  
Inspector: Marcus Hopkins

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	None	X				
Ceiling and Roof	None	X				
Walls	None	X				
Doors	None	X				