



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central  
County: Wood  
Site ID: 4-71-51-4  
Facility Type: Shed  
Site Address: 555 17<sup>th</sup> Ave. N., Wisconsin Rapids  
Date: March 28, 2016  
Inspector: Eric Schmidt

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	Large cracks and some potholes in asphalt apron.				X	
Ceiling and Roof	None		X			
Walls	None		X			
Doors	None		X			



Apron and Pad