



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central
County: Wood
Site ID: 4-71-54-1
Facility Type: Shed
Site Address: 5232 Second Ave., Pittsville
Date: March 28, 2016
Inspector: Eric Schmidt

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	Some cracks in apron.			X		
Ceiling and Roof	None		X			
Walls	Some cracks/deteriorating grout.			X		
Doors	Small hole in door panel.			X		



Apron and Pad



Walls



Doors