



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central
County: Wood
Site ID: 4-71-55-2
Facility Type: Shed
Site Address: 2300 South Galvin, Marshfield
Date: March 28, 2016
Inspector: Eric Schmidt

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	Some cracks; one large pothole in apron.				X	
Ceiling and Roof	None		X			
Walls	None		X			
Doors	None		X			



Apron and Pad