



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest  
County: Monroe  
Site ID: 5-41-702-1  
Facility Type: Shed  
Site Address: 603 Duane Street, Wilton  
Date: March 23, 2016  
Inspector: Dick Thompson

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	None		X			
Ceiling and Roof	None		X			
Walls	Inside wall board falling down (divider board between sites 5-41-702-1 & 5-41-702-1.			X		
Doors	Need some patching.			X		



Walls



Doors