



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest
County: Monroe
Site ID: 5-41-702-3
Facility Type: Shed
Site Address: 603 Duane Street, Wilton
Date: March 23, 2016
Inspector: Dick Thompson

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	None		X			
Ceiling and Roof	None		X			
Walls	Inside wall board falling down (divider board between sites 5-41-702-1 & 5-41-702-1.			X		
Doors	Need patching.			X		



Walls



Doors