



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central
 County: Oneida
 Site ID: 7-43-1-2
 Facility Type: Shed
 Site Address: 730 W. Kemp St., Rhinelander
 Date: March 8, 2016
 Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	Many weathered and missing shingles.				X	
Walls	Back wall is bowed out; one side is detached from truss. One side previously repaired.				X	
Doors	None		X			



Ceiling and Roof



Walls



Walls



Walls