



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central  
 County: Oneida  
 Site ID: 7-43-1-5  
 Facility Type: Dome  
 Site Address: 730 W. Kemp St., Rhinelander  
 Date: March 8, 2016  
 Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	Multiple areas of missing shingles.				X	
Walls	None		X			
Doors	None		X			



Ceiling and Roof



Ceiling and Roof



Ceiling and Roof



Ceiling and Roof