



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest
County: Pepin
Site ID: 6-46-1-1
Facility Type: Shed
Site Address: 609 Lake Street North, Pepin
Date: March 22, 2016
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	None		X			
Ceiling and Roof	None		X			
Walls	None	X				
Doors	None		X			