

Wisconsin Motor Vehicle
Crash Report[Print-Friendly Version](#)[Find all forms with this RD/CFS #](#)[Un-Redacted Version](#)

Document Number Override		Primary Crash Document #		Agency Crash Number		Investigating Officer/Deputy TROOPER J. PINKOS			
Crash Date 9/27/2018		Crash Time 2:15:00 PM		Date Arrived 9/27/2018		Time Arrived 2:39:00 PM			
Date Notified 9/27/2018		Time Notified 2:22:00 PM		Total Units 1		Total Injured 1	Total Killed 0		
<input type="checkbox"/>	On Emergency	<input type="checkbox"/>	Hit and Run	<input checked="" type="checkbox"/>	Lane Closure	<input checked="" type="checkbox"/>	Work Zone	<input checked="" type="checkbox"/>	Trailer or Towed
<input type="checkbox"/>	Government Property	<input type="checkbox"/>	Active School Zone	School Bus Related No		Tags			
<input checked="" type="checkbox"/>	Reportable	Crash Type DT4000 (Standard Crash)				<input type="checkbox"/>	Amended	<input type="checkbox"/>	Secondary Crash

Description

Reconstruction By	Photos By TPR J. PINKOS	Witness Statements, Photos, Other Documents
Narrative: I, a sworn law enforcement officer, I agree that I have not added any CJIS data in this report. I WAS DISPATCHED TO A CRASH AT MILEPOST 1 EASTBOUND ON I-94 WITH POSSIBLE INJURY AND A SEMI UNIT ON FIRE. WHEN I ARRIVED AT THE SCENE. I OBSERVED A SEMI TRUCK/TRACTOR (UNIT 1) FULLY ENGULFED IN FLAMES AND NO OTHER NON-EMERGENCY VEHICLES AT THE SCENE. A TRAFFIC CAMERA AT MILE POST 1 WAS FACING WEST AT THE TIME OF THE CRASH. IT CAPTURED THE INCIDENT AS IT TOOK PLACE. AFTER REVIEWING THE CAMERA FOOTAGE, UNIT 1 IS TRAVELING IN LANE 3 WEST ON I-94. UNIT 1 APPEARS TO SLOWLY DRIFT OUT OF ITS DESIGNATED LANE ONTO THE NARROW RIGHT HAND SHOULDER. THE VEHICLE TRAVELS UP THE SHOULDER AND STRIKES THE IMPACT ATTENUATOR AT THE END OF A WALL OF TRAFFIC BARRIERS. THE TRUCK TIPS ONTO ITS LEFT SIDE AND THEN BACK UP ONTO ITS TIRES. THE TRUCK IMMEDIATELY BURSTS INTO FLAMES AS IT TRAVELS OUT OF FRAME. WHEN THE CAMERA PANS OVER TO THE BURNING SEMI UNIT, THE DRIVER APPEARS TO BE WALKING AROUND ON THE FAR SIDE OF THE TRAFFIC BARRIERS. A STATEMENT WAS COLLECTED FROM THE DRIVER OF UNIT 1 WHICH DID NOT MATCH WHAT WAS SHOWN IN THE CAMERA FOOTAGE. PICTURES WERE TAKEN OF THE SCENE. VIDEO OF THE INCIDENT WAS RECEIVED FROM THE WISCONSIN TRAFFIC MANAGEMENT CENTER. THE DRIVER WAS CITED FOR FAILURE TO OPERATE IN DESIGNATED LANE.		

Location

ON INTERSTATE 94 EB 742 FT W OF 035 IN THE CITY OF HUDSON IN ST. CROIX COUNTY	Latitude 44.96263500	Longitude -92.75561454
	X Coordinate 46073.6796875	Y Coordinate 4994938
	Structure Type	

Crash Scene

First Harmful Event Impact Attenuator/Crash Cushion	First Harmful Event Location Shoulder Right
Manner of Collision No Collision W/Vehicle In Transport	Light Condition Daylight
Road Surface Condition(s) Dry	Roadway Factor(s) Work Zone (Construction/Maintenance/Utility), Narrow Shoulder

Wisconsin Motor Vehicle
Crash Report[Print-Friendly Version](#)[Find all forms with this RD/CFS #](#)[Un-Redacted Version](#)

Environment Factor(s) None					
Weather Condition(s) Cloudy					
Animal Type			Relation to Trafficway Trafficway - On Road		
Crash Classification - Location Public Property			Crash Classification - Jurisdiction No Special Jurisdiction		
Tribal Land			Access Control Full Control		Special Study
Within Interchange Area NO	Junction Location Non-Junction		Intersection Type Not an Intersection		
Work Zone Crash Location Activity Area		Work Zone Crash Type Lane Shift/Crossover			
Workers Present YES		Law Enforcement Present No			
Work Zone Speed Limit 60	Advisory/Regulatory Speed Limit Advisory		Normal Posted Speed Limit 70		
Closure Type Full closure		Reasons for Closure Law Enforcement, Tow truck, Fire/EMS			
Date Initial Lane/Road Closed 9/27/2018	Time Initial Lane/Road Closed 2:27:00 PM				
Date Scene Cleared 9/27/2018	Time Scene Cleared 9:48:00 PM		Date All Lanes Open 9/27/2018	Time All Lanes Open 9:48:00 PM	

Unit Summary -----

UNIT 1	Unit Status In Transit		Vehicle Operating As Classification A CLASS		Unit Type TRUCK	
	Vehicle Type Truck Tractor (Semi Attached)				Operating As Endorsements	
	Total Occs 1	Train/Bus # Injured	Total # Citations Issued 1		Total Trailers 1	Total HazMat Types 0
	Insurance? YES	Direction of Travel Eastbound	X	Pre Crash Tire Mark	Speed Limit 60	Total Lanes 3
	Most Harmful Event: Collision With Impact Attenuator/Crash Cushion		Special Function No Special Function		Emergency Motor Vehicle Use Not Applicable	
	Traffic Way Divided Hwy W/Traffic Barrier		Traffic Control NO CONTROL		Traffic Control Inoperative/Missing NO	
	Surface Type Blacktop (Bituminous)		Road Curvature Straight		Road Grade Uphill	
	Truck Bus or Hazmat Truck or truck combination > 10,000lbs GVWR/GCWR			Reporting Threshold		

Vehicle

Wisconsin Motor Vehicle
Crash Report[Print-Friendly Version](#)[Find all forms with this RD/CFS #](#)[Un-Redacted Version](#)UNIT
1

VEHICLE

UNIT
1

VEHICLE

UNIT
1VEHICLE
OWNER

License Plate Number PAT0545	Plate Type APO - Apportioned	St MN	Country of Issuance UNITED STATES
Vehicle Identification Number 1M1AW32Y2FM007542	Make MACK	Year 2015	Model MACK
Color WHI - White	Body Style TT - TRUCK TRACTOR GASOLINE	Bus Use Not A Bus	
Initial Contact Point 12--Front	Vehicle Damage		
Extent Of Damage Disabling Damage	All Areas		
Towed Due to Damage Towed Due To Disabling Damage	Vehicle Removed By JERRY'S TOWING		
What Driver Was Doing Going Straight	Vehicle Factors		
Driver Prior Action Other	Not Applicable		
Driver Actions Failed To Keep In Designated Lane			
Driver Distractions Unknown If Distracted			

Vehicle Owner

Organization/Company H AND S TRANSPORTATIONH AND S TRANSPORTATION (651) 470-5186	Address 33420 VALE DR NW CAMBRIDGE, MN 55008 , US
--	---

Sequence of Events

03	Event
04	Event
02	Event Concrete Traffic Barrier
01	Event Impact Attenuator/Crash Cushion

Policy Holder

Insurance Company INTEGRITY-MUTUAL-INS-CO	Organization/Company FINISH LINE EXPRESS LLC
---	--

Wisconsin Motor Vehicle
Crash Report[Print-Friendly Version](#)[Find all forms with this RD/CFS #](#)[Un-Redacted Version](#)UNIT
1TRAILER/
TOWED

Trailer/Towed

Trailer Plate # 722275	Plate Type STL - Semi	Make STOUGHTON	State WI	Country of Issuance UNITED STATES
Unit Type Semi Trailer	Organization/Company WREN EQUIPMENT			Address 2240 W SPENCER ST
Vehicle Identification Number 1DW1A5328HB75980	() -			APPLETON, WI 54914 , US

UNIT

INDIVIDUAL

Individual

Driver DWAYNE ROBERT MILLERS		Citations Issued 1		Phone Number (651) 706-0435	
		Date of Birth 09/17/1979		Sex M	Race WHITE
Address 478 HAZEL ST N #319 ST PAUL, MN 55119		Driver's License Number Redacted			
Equipment	On Duty Crash	Safety Equipment			
Seat Position 1--Front Seat-Left Side (Driver/Motorcycle/Bicycle)		Shoulder & Lap Belt			
Helmet Use		Helmet Compliance			
Eye Protection		Tint Compliance			
Injury	Injury Severity Suspected Minor Injury	Airbag Unknown			
Ejected Not Ejected		Ejection Path Not Ejected/Not Applicable		Trapped/Extricated Not Trapped	
Medical Transport EMS Ground		EMS Agency Identifier 6000594		EMS Run # 181307	
Hospital REGIONS HOSPITAL - ST. PAUL		Date of Death		Time of Death	
Non Motorist	Striking Unit #	Prior Action		Location	To/From School
Action					
Action Other					
Drug & Alcoh	NO	Suspected Alcohol Use		NO	Suspected Drug Use

01

001

UNIT

INDIVIDUAL

01

001

Wisconsin Motor Vehicle
Crash Report[Print-Friendly Version](#)[Find all forms with this RD/CFS #](#)[Un-Redacted Version](#)

UNIT

INDIVIDUAL

Alcohol Test Given Test Not Given	Alcohol Test Type	Alcohol Test Results
Drug Test Given Test Not Given	Drug Test Type	Drug Test Results
Drug Type		
Individual Condition Appeared Normal		

01

Violations

UTC Number BD067710	Issue to? 001	Statute Number 346.13(3)	Seq Num 001	Description DEVIATION FROM DESIGNATED LANE
-------------------------------	-------------------------	------------------------------------	-----------------------	--

Carrier

<input type="checkbox"/>	Use Vehicle Owner Same as Carrier	Carrier Name FINISH LINE EXPRESS LLC	Source Vehicle-Side					
Name FINISH LINE EXPRESS LLC USDOT# 2889118		Address 50 14TH ST NW NEW BRIGHTON, MN 55112 , US						
GVWR More Than 26,000 Lbs	Vehicle Configuration Truck Tractor/Semi-Trailer		Cargo Body Type Van/Enclosed Box					
US DOT # 2889118		Carrier Type Interstate Carrier	Permitted Load Not Applicable					
<input type="checkbox"/>	OS/OW Load	WI Permit Number	<input type="checkbox"/>	Permitted Vehicle On Permitted Route	<input type="checkbox"/>	Escort Vehicle Required By Permit	<input type="checkbox"/>	Escort Vehicle Present
Measured Height		Measured Length		Measured Width		Measured Weight		

UNIT
1

TRUCK BUS

Wisconsin Motor Vehicle Crash Report



[Print-Friendly Version](#)



[Find all forms with this RD/CFS #](#)

[Un-Redacted Version](#)

Property Owner -----

01 PROP OWNER	Organization/Company	Address
	CHIPPEWA CONCRETE (715) 210-1515	3030 110TH ST CHIPPEWA FALLS, WI 54729 , US

Fixed Objects Struck

01	Striking Unit 1	Struck Object Impact Attenuator/Crash Cushion	Damage Tag Number 352436
02	Striking Unit 1	Struck Object Concrete Traffic Barrier	Damage Tag Number 352437
03	Striking Unit 1	Struck Object Concrete Traffic Barrier	Damage Tag Number 352426
04	Striking Unit 1	Struck Object Concrete Traffic Barrier	Damage Tag Number 352427
05	Striking Unit 1	Struck Object Concrete Traffic Barrier	Damage Tag Number 352428
06	Striking Unit 1	Struck Object Concrete Traffic Barrier	Damage Tag Number 352429