

ATTACHMENT C  
PHOTOS OF DEFICIENT AREAS

1050-01-11  
Chippewa Falls – Abbotsford  
Stillson Creek to Cardinal Ave  
STH 29  
Chippewa and Clark Counties  
Structure Photos

**B-10-178**



**Top of Deck**



**West end of deck looking south - spalling**





**NW end of deck – Asphalt patch**



**North end of Deck**





North end of deck



**North End of Deck – Asphalt patch**





**SE Wing - Tipping**





**SE Wing - Tipping**



**SE Wing –Tipping**





**SE Wing -Tipping**



**SW Wing – Tipping (< 0.5 inches)**





**SW Wing – Tipping (< 0.5 inches)**



**NW Wing - Tipping**





**NW Wing - Tipping**



**NW Wing - Spalling**





**NW Wing – Spalling**





**NW Wing – Spalling**





**NW Wing – Tipping and Spalling**



**NE Wing - Tipping**





**NE Wing – Tipping and Spalling**