

STH 93 NB BRIDGE – B-18-0119 – March 25, 2019 - Temp = 43 degrees



NORTH APPROACH – LOOKING SOUTH



SIDEWALK – LOOKING NORTH



NW WING TIPPING



NW WING DETERIORATION



NW WING TIMBER SUPPORTS



NE WING



NORTH DECK JOINT



SW WING



SOUTH ABUTMENT BACKWALL



NORTH ABUTMENT BACKWALL



PIER 1 COLUMN



SE QUAD FENCE